



# SA305

## PRELIMINARY DEVICE ERRATA

This document describes the errata information for the SA305 device in the 23 pin SIP package style EX.

ERRATA NUMBER	DESCRIPTION	IMPACT & WORK AROUND
1	Undervoltage lockout thresholds differ from the values specified in the datasheet.	Impact: V <sub>S</sub> supply undervoltage positive going threshold: 13V. V <sub>S</sub> supply undervoltage negative going threshold: 10V.